7-14-05 09/587,09\$ c.fc.



July 13, 2005

Michael P. Brennan Direct Dial: 248.641.1218 mbrennan@hdp.com

Director of the U.S. Patent and Trademark Office P. O. Box 1450 Alexandria, VA 22313-1450

Re:

U.S. Patent No. 6,885,879 Issued: April 26, 2005 Inventors: Pierre Got et al.

For:

Battery Reconnect System for a Telecommunications Power System

Certificate

JUL 2 1 2005

of Correction

Sir:

In proofreading the above identified application, the following error was noted which appears to require a Certificate of Correction:

Column 5, line 60 (application page 11, line 1), "leas" should be -leads--.

Enclosed herewith is an original and a copy of the Patent and Trademark Office Certificate of Correction form which we request be approved for the above identified patent.

The Director is hereby authorized to charge any additional fees which may be required in connection with this correction to Deposit Account No. 08-0750. A duplicate copy of this letter is enclosed.

Respectfully submitted,

Michael P. Brennan Reg. No. 30,612

MPB/rc Enclosure

> FOR COURIER DELIVERY ONLY Harness, Dickey & Pierce, P.L.C. Attorneys and Counselors 5445 Corporate Drive Troy, Michigan 48098 248.641.1600

CABLE
Patents Troy, Michigan
Telex No. & Reply
287637 Harness UR
Telefacsimile 248.641.0270

P.O. Box 828 Bloomfield Hills, MI 48303 U.S.A.

2 2 2005

www.hdp.com 2 20



Michael P. Brennan

Direct Dial: 248.641.1218

mbrennan@hdp.com



July 13, 2005

Director of the U.S. Patent and Trademark Office P. O. Box 1450 Alexandria, VA 22313-1450

Re:

U.S. Patent No. 6,885,879

Issued: April 26, 2005 Inventors: Pierre Got et al.

Battery Reconnect System for a

Telecommunications Power System

Sir:

In proofreading the above identified application, the following error was noted which appears to require a Certificate of Correction:

Column 5, line 60 (application page 11, line 1), "leas" should be -leads--.

Enclosed herewith is an original and a copy of the Patent and Trademark Office Certificate of Correction form which we request be approved for the above identified patent.

The Director is hereby authorized to charge any additional fees which may be required in connection with this correction to Deposit Account No. 08-0750. A duplicate copy of this letter is enclosed.

Respectfully submitted,

Michael P. Brennan Reg. No. 30,612

MPB/rc Enclosure

> FOR COURIER DELIVERY ONLY Harness, Dickey & Pierce, P.L.C. Attorneys and Counselors 5445 Corporate Drive Troy, Michigan 48098 248.641.1600

Patents Troy, Michigan Telex No. & Reply 287637 Harness UR Telefacsimile 248.641.0270

P.O. Box 828 Bloomfield Hills, MI 48303 U.S.A.

Metropolitan

Detroit, MI St. Louis, MO Washington, D.C.

2 2005

www.hdp.com

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO:

6,885,879

DATED:

April 26, 2005

INVENTOR(S): Pierre Got et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 5,

Line 60, "leas" should be -leads--..

MAILING ADDRESS OF SENDER:

Michael P. Brennan, Esq. Harness, Dickey & Pierce, P.L.C. P.O. Box 828 Bloomfield, MI 48303

6,885,879

PATENT NO.

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

2005 ·

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO:

6,885,879

DATED:

April 26, 2005

INVENTOR(S): Pierre Got et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 5,

Line 60, "leas" should be -leads--..

MAILING ADDRESS OF SENDER:

Michael P. Brennan, Esq. Harness, Dickey & Pierce, P.L.C. P.O. Box 828 Bloomfield, MI 48303

6.885.879

PATENT NO.

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS, SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.



Patent No. 6,885,879

torney Docket No. 3165A-000007

Express Mail Label No. EV 570 164 764 US (7/13/2005)

Certificate of Mailing under 37 CFR 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service with sufficient postage as express mail in an envelope addressed to:

> Director of the United States Patent and Trademark Office P.O. Box 1450 Alexandria, VA 22313-1450

on July 13, 2005.

Date

Signature

Michael P. Brennan

Typed or printed name of person signing Certificate

Note: Each paper must have its own certificate of mailing, or this certificate must identify each submitted paper.

Submitted herewith is (are):

Certificate of Correction Transmittal (in duplicate)
Certificate of Correction PTO/SB/44 Form (in duplicate)
Return Postcard